

SECTION CORNER RECORD VERMILLION COUNTY SURVEYOR'S OFFICE

BL9



The stone was found in place and held as marking the corner. This corner has been previously documented by Ben E. Bledsoe, LS No. S0559, as part of a Vermillion County Monument Record dated February 9, 1997, which references a survey recorded as Survey Record 1, page 450. The stone is also referenced on a survey by the same surveyor recorded as Survey Record 1, pages 455-459. The stone is referenced on other recorded surveys, including Instrument 2017002109 and 2020000334, and a recent, unrecorded survey by Hause Surveying & Engineering, dated March 7, 2023. The stone was located on March 9, 2023. The above-ground portion of the stone is 6 inches N-S by 8 inches E-W with a distinct high point. Adjacent to the stone on the southeast side is another rock which appears to be bracing the main stone. This brace stone is etched with markings "N.W. 33" indicating the northwest corner of section 33.

The stone is witnessed by a steel t-post with white PVC sleeve labelled 'Survey Marker.'



Vermillion Township

Section 29 T17N, R9W
Section 28 T17N, R9W
Section 32 T17N, R9W
Section 33 T17N, R9W